

## Super Seaking V7 Bathymetric Sensors that use Seanet Pro v2.24 require RemV4 software update to output survey data.

The issues effects:

- Tritech V7 Bathymetric Sensors.
- Seanet Pro versions up to V2.24 (03/02/2020).

A patch is available for Seanet Pro RemV4 for use with V7 Sensors from the Tritech website here:

<https://www.tritech.co.uk/support-software/seanet-pro-v2-24>

Download the Patch listed as:

**REM V4 PATCH FOR BATHY V7**  
**03/03/2020 | SIZE: 5.6MB**

The patch updates Seanet to ensure RemV4 outputs have the latest data-string formats to operate with the Super SeaKing V7 Bathy,

Users should install the patch from the above link before attempting to output survey data with RemV4.

This patch will be included in the next full release of Seanet Pro.

This does not affect customers using Tritech's Genesis Software.

Further product information and support is available from Tritech via:

Tel: +44 (0)1224 744111  
Email: [Tritech-support@moog.com](mailto:Tritech-support@moog.com)  
Web: [www.moog.com/tritech](http://www.moog.com/tritech)